








Work Order ID 57498

Wednesday, April 07, 2010 2:29:34 PM

Page 1

Item ID:	D3179-041	Accept		Setup	Start	
Revision ID:					Stop	
Item Name:	Fwd Litter Tie Down					
Start Date:	4/7/2010	Start Qty:	1.00		Cust Item ID:	
Required Date:	4/7/2010	Req'd Qty:	1.00		Customer:	
Reference:	Return 2009 / RA109033					

Approvals:	Process Plan:	Date:	Tooling:	Date:	Run	Start	
	QC:	Date:	SPC (Y/N):	Date:		Stop	


Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3179	Rev C

100	QC5- Inspect part completeness to step on W/O	0.00
-----	---	------

	QC	Memo	0.00	<u>1</u>	<u>1004-07</u>
Quality Control		Original B43973. Now used for eng & show use.			

110	QC21- Final Inspection - Work Order Release	0.00
-----	---	------

	QC	Memo	0.00	<u>10</u>	<u>04</u>	<u>07</u>
Quality Control						

10/04/12
MF
10-4-9